Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513			
Inspection Date(s): 2/10/2015, 2/11/2015	Man Days: 2			
Inspection Unit: Tuscola	·			
Location of Audit: Philo, Sidney, Pesotum, Villa Grove, Tolono, Longview, Sidney, Tuscola, Atwood, Bourbon				
Exit Meeting Contact:				
Inspection Type: Standard Inspection - Field Audit				
Pipeline Safety Representative(s): Aaron McElravy				
Company Representative to Receive Report: Michael Fuller				
Company Representative's Email Address: mfuller2@ameren.com				

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#: (800) 755-5000	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
Dallas Jett	Superintendent Quality Assurance	(217) 556-2605

Category Comment:	
Customer meters were inspected at the following	g locations for protection from damage, venting requirements, stress, meter case ratings and valve requirements.
Tuscola	
303 Holiday Meter #2095586	
300 N. Central Meter #20920699	
302 N. Central Meter #01B571181	
807 S. Barker Meter #01B571199	
Trailer #37 Barker Meter #20723436	
Trailer #39 Barker Meter #00313954	
201 E. Daggy Meter #20530769	
209 E. Daggy Meter #99Z839888	
211 E. Daggy Meter #240829	
Arthur	
825 E. Columbus Meter #21413741	
421 E. & 200 N Meter #21413791	
447 E. & 200 N Meter #20827111	
455 E. & 200 N Meter #20826773	
457 F. & 200 N Meter #21413756	

**Status** 

**CUSTOMER METER & REGULATOR** 

[192.353(a)]	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Satisfactory
[192.355(b)(1)]	Is the customer regulator vent rain and insect resistant?	Satisfactory
[192.355(b)(2)]	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Satisfactory
[192.355(b)(3)]	Is the vent protected from damage caused by submergence in areas of flooding?	Satisfactory
[192.357(a)]	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Satisfactory
[192.357(d)]	Is a customer regulator that might release gas vented to the outside atmosphere?	Satisfactory
[192.359(a)]	Is the meter operating pressure within the allowable limits of the meter case rating?	Satisfactory
[192.365(a)]	Is the service line valve upstream of the regulator or meter?	Satisfactory
[192.365(c)]	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Satisfactory
General Comment:		
Staff inspected an undergroui	nd service line valve located at 409 S. Prairie Street in Tuscola. This valve is utilized for isolation of the Ea	st Prairie Middle School.
	md service line valve located at 409 S. Prairie Street in Tuscola. This valve is utilized for isolation of the Eal  When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	st Prairie Middle School.  Satisfactory
	] When service to the customer has been discontinued has the proper method	
[192.727(d)][192.727(d)	] When service to the customer has been discontinued has the proper method	
[192.727(d)][192.727(d)	] When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	
[192.727(d)][192.727(d)	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.	Satisfactory
[192.727(d)][192.727(d)  General Comment:  Staff verified a locking device	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part	Satisfactory Status
[192.727(d)][192.727(d)  General Comment:  Staff verified a locking device  [192.463(a)]  General Comment:	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part	Satisfactory Status
[192.727(d)][192.727(d)  General Comment:  Staff verified a locking device  [192.463(a)]  General Comment:	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Satisfactory Status
[192.727(d)][192.727(d)  General Comment:  Staff verified a locking device  [192.463(a)]  General Comment:  All facilities listed were inspec	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?  sted for adequate cathodic protection levels.	Satisfactory  Status  Satisfactory
[192.727(d)][192.727(d)]  General Comment: Staff verified a locking device  [192.463(a)]  General Comment: All facilities listed were inspect  [192.465(a)]  General Comment:	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?  sted for adequate cathodic protection levels.	Satisfactory  Status  Satisfactory
[192.727(d)][192.727(d)  General Comment: Staff verified a locking device  [192.463(a)]  General Comment: All facilities listed were inspect  [192.465(a)]  General Comment: Pipe to soil readings were obtated to soil	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?  cited for adequate cathodic protection levels.  Were pipe to soil readings taken?  tained from the following locations during the field audit.  Pipe to Soil Reading	Satisfactory  Status  Satisfactory
[192.727(d)][192.727(d)  General Comment:  Staff verified a locking device  [192.463(a)]  General Comment:  All facilities listed were inspect  [192.465(a)]  General Comment:  Pipe to soil readings were obtance of the control of th	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?  sted for adequate cathodic protection levels.  Were pipe to soil readings taken?  tained from the following locations during the field audit.  Pipe to Soil Reading er # 20920699 -1.258volts	Satisfactory  Status  Satisfactory
[192.727(d)][192.727(d)  General Comment:  Staff verified a locking device  [192.463(a)]  General Comment:  All facilities listed were inspect  [192.465(a)]  General Comment:  Pipe to soil readings were obtance of the control of th	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?  Steed for adequate cathodic protection levels.  Were pipe to soil readings taken?  tained from the following locations during the field audit.  Pipe to Soil Reading er # 20920699 -1.258volts er #018571181 -1.222volts	Satisfactory  Status  Satisfactory
[192.727(d)][192.727(d)  General Comment:  Staff verified a locking device  [192.463(a)]  General Comment:  All facilities listed were inspect  [192.465(a)]  General Comment:  Pipe to soil readings were obtained by the soil reading were obtaine	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?  Steed for adequate cathodic protection levels.  Were pipe to soil readings taken?  tained from the following locations during the field audit.  Pipe to Soil Reading er # 20920699 -1.258volts er #018571181 -1.222volts or #018571199 -1.35volts	Satisfactory  Status  Satisfactory
[192.727(d)][192.727(d)  General Comment:  Staff verified a locking device  [192.463(a)]  General Comment:  All facilities listed were inspect  [192.465(a)]  General Comment:  Pipe to soil readings were obtance of the control of th	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?  sted for adequate cathodic protection levels.  Were pipe to soil readings taken?  tained from the following locations during the field audit.  Pipe to Soil Reading er # 20920699	Satisfactory  Status  Satisfactory
[192.727(d)][192.727(d)  General Comment:  Staff verified a locking device  [192.463(a)]  General Comment:  All facilities listed were inspect  [192.465(a)]  General Comment:  Pipe to soil readings were obtained by the soil re	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?  was used to prevent unauthorized usage at 103 N. Main in Atwood, IL.  CATHODIC PROTECTION  Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?  Sted for adequate cathodic protection levels.  Were pipe to soil readings taken?  Were pipe to Soil Reading er # 20920699 -1.258volts er #01B571181 -1.222volts er #01B571199 -1.35volts -1.31volts -1.33volts -1.33volts -1.33volts -1.33volts -1.33volts -1.272volts -1.272vo	Satisfactory  Status  Satisfactory

[192.465(b)]	Were rectifier installations inspected?	Satisfactory
General Comment:	<u> </u>	
	has one rectifier located in Sidney, IL Test Point ID T-074-002-R, Staff observed the corrosion tech inspe following readings were observed 1.1 amps / 5.25volts.	ct and obtain readings
[192.465(a)]	Were isolated mains/services tested?	Satisfactory
General Comment:		
Staff observed a reading of	-1.421volts obtained on an isolated 2 inch service located at 401 S. Center Street in Tuscola, IL. Test Poi	nt ID TU-SP184600721
192.465(c)]	Were critical/non critical bonds tested?	Not Applicable
General Comment:		
Ameren's Tuscola inspection	n unit does not contain critical or non-critical bonds.	
[192.467(a)] Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?		
General Comment:	•	
Staff observed Isolation dev	rices on the listed facilities inspected during this audit which included insulated meter components and iso	lation flanges.
192.467(c)]	Were casings installations tested for electrical isolation?	Satisfactory
General Comment:		•
Staff observed cathodic pro	tection readings obtained on casings during the field audit.	
Test Point Location	Reading	
T-002-002-CS Tuscola	Casing -1.097volts / Pipe -1.258volts	
T-002-001-CS Tuscola	Casing -0.988volts	Ī
192.479(a)]	Is the above ground piping coated or painted as required?	Satisfactory
General Comment:		-
All facilities listed were inspe	ected for adequate coatings to prevent atmospheric corrosion.	
92.479(c)] Is the pipeline free of corrosion or pitting?		Satisfactory
General Comment:		-
All facilities listed were free	of corrosion or pitting.	
	DAMAGE PREVENTION	Status
192.614]	Does the operator have a valid notification of planned excavation activities?	Satisfactory
General Comment:		
Staff observed a post audit i	for the location of facilities at the following locations during the field audit.	
Locate # Location		
X000360530 284 Cd	ounty Road 425 E. Bourbon, IL ounty Road 425 E. Bourbon, IL	
X000360533 276 Cd	ounty Road 425 E. Bourbon, IL	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Did the operator complete the locating activities in the specified timeframe?

[205.40(a)]	Did the operator complete the locating activities in the specified timename:	Satisfactory
[192.614(c)(5)]	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Satisfactory
[192.707(a)(1)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Satisfactory
General Comment:		
	t various location during the field audit for placement requirements, Staff inspected the following line ma formation at the following locations.	rkers for the required
[192.707(a)(2)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Satisfactory
[192.707(c)]	Are line markers placed and maintained as close as practical over each main and transmission line located above ground?	Satisfactory
[192.707(d)(1)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Satisfactory
[192.707(d)(2)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	Satisfactory
PRESSURE	LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
supports, venting requirements	ressure limiting and regulating devices during the field audit for proper installation, protection from dama s and isolation to prevent unauthorized operation of a stop valve.  Inlet MAOP Outlet MAOP Inlet Pressure Outlet Pressures	ge, set pressures,

Station ID	Location	ITITELIVIAUP	Outlet WAOP	Illiet Flessule	Ouliet Flessules
XT-033	Philo	300psig	44psig	267psig	39psig
XT-035	Sidney	300psig	54psig	268.8psig	50.4psig
XT-032	Pesotum	100psig	60psig	95psig	47.9psig
XT-039	Villa Grove	100psig	25psig	92.6psig	22.5psig
XT-03	Sidney	300psig	300psig	267psig	267psig
XT-037	Tolono	300psig	50psig	199.7psig	47.2psig
XT-016	Longview	300psig	63psig	265psig	34.3psig
,		1			<u> </u>

[192.739(a)(4)] Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not

[265.40(a)]

Satisfactory

	exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?			
[192.317(b)]	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?			
[192.741(a),192.741(c)]	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Satisfactory		
[192.743(a)]	Is overpressure protection provided on the pipeline down stream of the take point?			
General Comment:				
Ameren has identified location	ns requiring additional protection and has devised a plan to add additional facilities.			
[192.199(d)]	Were the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory		
[192.199(e)]	Were the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?			
	· ·			
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Satisfactory		
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will	Satisfactory Status		
[192.199(h)] [192.747(a)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	-		
	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the	Status		
General Comment:	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the	Status		
[192.747(a)]  General Comment:	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?	Status		
[192.747(a)]  General Comment:  Emergency Valves were inspective ID Location T-02-003 800 N & Center Comments	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?  Accepted for accessibility at the following locations.	Status		
[192.747(a)]  General Comment:  Emergency Valves were inspective ID Location  T-02-003 800 N & Centre T-03-001 Cleveland S	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?  Accepted for accessibility at the following locations.	Status		
[192.747(a)]  General Comment:  Emergency Valves were inspective ID Location  T-02-003 800 N & Centrol Cleveland Street T-03002 Philo	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?  Acted for accessibility at the following locations.	Status		
[192.747(a)]  General Comment:  Emergency Valves were inspectively Valve ID Location  T-02-003 800 N & Ce.  T-03-001 Cleveland St.  T-03002 Philo  T-04-001 Main St, Sic.	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?  Acted for accessibility at the following locations.  Antral Avenue, Tolono  St. Philo  Idney	Status		
[192.747(a)]  General Comment:  Emergency Valves were inspectively below the second of	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?  Acted for accessibility at the following locations.  Security Avenue, Tolono Set, Philo Idney Security Avenue, Tolono Security Avenue,	Status		
[192.747(a)]  General Comment:  Emergency Valves were inspectively below the second of	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?  Acted for accessibility at the following locations.  Security Avenue, Tolono Set, Philo Idney Security Avenue, Tolono Security Avenue,	Status		
[192.747(a)]  General Comment:  Emergency Valves were inspectively below the series of	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?  Acted for accessibility at the following locations.  Antral Avenue, Tolono  St. Philo  Grey  B  TB	Status		
[192.747(a)]  General Comment:  Emergency Valves were inspectively below the series of	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?  VALVE MAINTENANCE  Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?  **Cotted for accessibility at the following locations.**  **Intral Avenue, Tolono**  St. Philo**  **Intral Avenue, Tolono**  **Intral Avenue, Tolono**	Status		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

**ODORIZATION OF GAS** 

192.625(a)]	Was the odor intensity level readily detectable at or below 1/5th LEL?	Satisfactory	
General Comment:			
Ameren obtained an odo	rant intensity reading of .50% gas-in-air on February 10, 2015 at Test Point #T-56 108 N. Sycamore Villa Gro	ve, IL.	
[192.625(e)] Was the Odorization equipment and tank levels inspected?			
General Comment:			
Staff checked odorant ta	nk levels at the following locations during the field audit.		
Station ID Location XT-032 Pesotum XT-003 Sidney			
192.625(f)]	Was the operator's equipment calibrated as required?	Satisfactory	
General Comment:	•		
Ameren utilized a Heath	Odorator Serial # 1763 which was calibrated 12-12-2014.		
	TRANSMISSION	Status	
Category Comment:			
Staff conducted a field a	udit of the distribution system, the Tuscola inspection unit does not maintain transmission pipelines.		
[192.179(b)(1)]	Are transmission valves protected from tampering or damage?	Not Applicable	
[192.745(a)]	Were the valves inspected accessible?	Not Applicable	
[192.719(a)]	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Applicable	
	MARKING OF MATERIAL	Status	
[192.63(a)]	Does the operator's components and pipe contain the required markings?	Satisfactory	
General Comment:			
	d during the field audit contained the required markings to indicate the size, manufacturer, pressure rating and	d model of equipment.	
	d during the field audit contained the required markings to indicate the size, manufacturer, pressure rating and	d model of equipment.  Status	

Employee ID

#38413 (Gas Regulator Tech)

#57065 (Corrosion Control Tech)

#37737 (Gas Journeymen)

#38485 (Gas Journeymen)

Name

John Rairden

Jeff Rodmaker

Christi Arthur

Mary Harris

**Status** 

OQ Date

8-27-2014

3-28-2013

4-2-2012

4-15-2014